




Industrial & commercial applications may require the installation of a LOCKOUT/TAGOUT device to prevent the kiln from operating during maintenance.

This kiln is recommended to be wired & connected to an approved U. L. & NEC configured receptacle controlled with a disconnect switch and properly fused according to the kW load specification listed on the kiln nameplate. L&L Kiln Mfg., Inc., also recommends fuses rather than circuit breakers to prevent nuisance tripping.

Wiring Information			
Power	10AWG / 150°C / 600V		
Control	16-22AWG / 105°C / 600V		
Power Supply Wire Gauge assumes 75°C Copper Wire. See hotkilns.com/wire-size.			

Model: DL11-D			
Voltage	120 / 1 / 50-60		
Watts	1,800		
Full Load Amps	L1	L2	L3
	15.0	15.0	
Power Supply	Fuse	Wire	
	20A	14AWG	
Elements	QTY	OHMS	
	3	2.5	

DL11-D 1 Phase 120V			 505 Sharptown Road Swedesboro NJ 08085 service@hotkilns.com (856)-294-0077 Drawn by: JS C0039
Rev.	Date	Description	