




Industrial & commercial applications may require the installation of a LOCKOUT/TAGOUT device to prevent the kiln from operating during maintenance.

This kiln is recommended to be wired & connected to an approved U. L. & NEC configured receptacle controlled with a disconnect switch and properly fused according to the kW load specification listed on the kiln nameplate. L&L Kiln Mfg., Inc., also recommends fuses rather than circuit breakers to prevent nuisance tripping.

Wiring Information	
Power	10AWG / 150°C / 600V
Control	16-22AWG / 105°C / 600V
Power Supply Wire Gauge assumes 75°C Copper Wire. See hotkilns.com/wire-size.	

Model: DLH11-D	
Voltage	120 / 1 / 50-60
Watts	2,160
Full Load Amps	L1 18.0 L2 18.0 L3
Power Supply	Fuse 25A Wire 12AWG
Elements	QTY 3 OHMS 2.04
E-D-DHLS/11	

DLH11-D 1 Phase 120V			 505 Sharptown Road Swedesboro NJ 08085 service@hotkilns.com (856)-294-0077 Drawn by: JS C0040
Rev.	Date	Description	