




Industrial & commercial applications may require the installation of a LOCKOUT/TAGOUT device to prevent the kiln from operating during maintenance.

This kiln is recommended to be wired & connected to an approved U. L. & NEC configured receptacle controlled with a disconnect switch and properly fused according to the kW load specification listed on the kiln nameplate. L&L Kiln Mfg., Inc., also recommends fuses rather than circuit breakers to prevent nuisance tripping.

WIRE & PLUG NOT INCLUDED
DIRECT WIRE TO BREAKER PANEL OR FUSED DISCONNECT.

Model: eFL1626-480-3P			
Voltage	480 / 3 / 50-60		
Watts	12,500		
Full Load Amps	L1	L2	L3
	15.0	15.0	15.0
Power Supply	Fuse	Wire	
	20A	14AWG	
Elements	QTY	OHMS	
E-H-1626/60	6	35.4	

eFL1626 3 Phase 480V 480V			 505 Sharptown Road Swedesboro NJ 08085 service@hotkilns.com (856)-294-0077 Drawn by: JS C0075
Rev.	Date	Description	