



Wiring Information	
Power	10AWG / 150°C / 600V
Control	16-22AWG / 105°C / 600V
Power Supply Wire Gauge assumes 75°C Copper Wire. See hotkilns.com/wire-size.	

Model: e18S-208		
Voltage	208 / 1 / 50-60	
Watts	4,980	
Full Load Amps	L1	L2 L3
	23.9	23.9
Power Supply	Fuse	Wire
	30A	10AWG
Elements	QTY	OHMS
E-E-18SL/21	4	8.36

Model: e18S-240		
Voltage	240 / 1 / 50-60	
Watts	5,740	
Full Load Amps	L1	L2 L3
	23.9	23.9
Power Supply	Fuse	Wire
	30A	10AWG
Elements	QTY	OHMS
E-E-18SL/31	4	9.66

Industrial & commercial applications may require the installation of a LOCKOUT/TAGOUT device to prevent the kiln from operating during maintenance.

This kiln is recommended to be wired & connected to an approved U. L. & NEC configured receptacle controlled with a disconnect switch and properly fused according to the kW load specification listed on the kiln nameplate. L&L Kiln Mfg., Inc., also recommends fuses rather than circuit breakers to prevent nuisance tripping.

E18S Easy-Fire 1 Phase 208V, 240V (C0008)					
				505 Sharptown Road Swedesboro NJ 08085 service@hotkilns.com (856)-294-0077	
A	05/12/2026		AF	Drawn by: AF	
Rev.	Date	Description	Approved by	Dwg. No. C0008	