



ELECTRICAL PARTS LIST

SYMBOL	QTY	DESCRIPTION	CUSTOMER PART NO.
1TB	1	POWER CONNECTION BOARD	L-J-PBLG/02
1TAS	1	BARTLETT DYNATROL	N-G-D300/00
T/C.	3	THERMOCOUPLES (8 Ga)	T-G-E800/00
CONN	1	CABLE AND CONNECTOR FOR PANEL	L-G-CTFM/00
JACK	1	CABLE AND JACK FOR CONTROL	L-G-CTML/00
1FU	1	CONTROL FUSE	L-C-FS05/00
1FUB	1	PANEL MOUNT FUSE HOLDER	L-G-FSPB/00
1TGS	1	ON/OFF TOGGLE SWITCH	L-G-SWTG/00
XFRMR	1	STEP DOWN TRANSFORMER	L-G-TR24/LG
1-4MOV	4	31 VOLT SURGE SUPPRESSORS	L-G-MOV0/00
C	4	POWER RELAYS	L-G-RL25/12
FU	8	ELEMENT FUSES	L-G-FS30/NL
FUB	4	ELEMENT FUSE BLOCKS	L-G-FH30/20
R	4	SINGLE RECEPTACLE NEMA 6-20R	L-G-SR20/00
2TAS	1 (OPT)	DAWSON KILN SITTER	N-G-LT30/00
2TAS	1 (OPT)	50 HZ DAWSON KILN SITTER	N-G-LT30/50

505 SHARPTOWN ROAD
SWEDDESBORO, NJ 08085

PHONE: (856) 294-0077
FAX: (856) 294-0070

hotkilns.com

CONTROL WIRING DIAGRAM
WITH HAND-HELD DYNA-TROL
For 3 Phase KILN with (4) 20 Amp Sections
Branch Circuit Fusing / No Power Bottom

DRAWN BY	G.W.L.	REV. CODE		DRAWING NO.	
DATE	1/31/01	SCALE	1 = 8	A	K262-164
CHK	G.D.L.	APP			
JOB NO		SER NO		SHEET NO.	1 OF 1
FILE NAME	L:\EVLKILN\WIRING\K262-164.dwg		MADE FROM	L:\SERIES\K038-151.dwg	